

# Manhole Inspection Summary

Manhole # S13KK\_038MH

Printed On: 8/6/2009

Page 1 of 3

**Inspection** ☒ **Is Incomplete** Rating:

Record Plat: **13KK** Node: **038** Status: **Found**

Insp Date: **7/22/09 9:11 AM**

Incomplete Comments

**Cannot Access - Buried - Manhole Existing Confirmed by CCTV**

Crew:  
Inspector: **ADS2**  
Firm:

**Location** Address: **BEHIND 2819 WINDSOR AVE** Cross Street: **N DUKELAND ST**

**Manhole** Type: Location: **Alley** Ground Conditions:  
☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **None**

Comments **MH LOCATED UNDER DEBRIS SEE LOCATION PICTURES**

**Cover** Shape: Diameter: (in.) Length: (in.) Dist A/B Grade: (in.)  
Type: **Sanitary** Condition: Cover Material: **Cast Iron**  
Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

**Frame** Offset: (in.) Condition: ☐ Sound ☐ Cracked ☐ Leaks

**Chimney / Frame Adjustment** ☐ Exists Material: ☐ Parged Height: (in.)  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Corbel** Material: ☐ Parged Type:  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Barrel** Material: ☐ Parged  
Shape: Diameter: (in.) Length: (in.)  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Bench** ☐ Exists Material: ☐ Parged  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Channel** Material: ☐ Parged  
Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Steps** Count: Missing: ☐ Corroded

**Surcharge** ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

Location View



